



Example of Labview block diagram




Example of Labview block diagram

TLA trigger circuit –provides signal to PG Event trigger




Example of Labview block diagram




Ke 2400 sourcemeter – to ramp gate (V_{gs})

Example of Labview block diagram



Ke 6485 picoammeter sections – to measure current in range of pA to uA range

Example of Labview block diagram



Data recording/plotting section
-dumps data to tdms file or csv format
- plots data in labview